

SSS Ultron 20BA Operator Guide

PREPARATION:




SWEEP OR DUST MOP the surface to be cleaned for best results. Remove any large debris from the floor.



CHECK BATTERY LEVEL if needed fully charge the batteries with on-board battery charger before using. Refer to the owner's manual for detailed instruction. Unplug the power cord when done.



CHECK PAD DRIVER/BRUSH to make sure both are CLEAN and properly installed. To install: 1) Turn off the machine. 2) Step down the foot pedal to raise the scrub head. 3) Mount the pad driver/brush to the brush motor hub by lining up the three studs with the three holes. 4) Rotate the driver toward the spring clip to lock the pad driver. If necessary, press down the lock pin to lock motor hub.



CHECK SQUEEGEE ASSEMBLY to ensure it is ready for use. Be sure vacuum hose is properly connected and clipped in place. See manual for squeegee assembly installation.

OPERATION:



FILL SOLUTION TANK WITH HOSE, Solution tank can be filled from the rear port with a hose or in the front (step 2).



OR USE FRONT FILL PORT WITH BUCKET



CHECK SITE TUBE for solution level before scrubbing, make sure there is enough in tank, add more solution if needed.



TURN ON THE MAIN POWER KEY SWITCH



LOWER BRUSH/PAD DECK DOWN with step down the foot pedal to the left side.



LOWER SQUEEGEE ASSEMBLY TO THE FLOOR by lowering the squeegee lift lever.



CHECK BRUSH PRESSURE setting before scrubbing, for normal daily scrubbing lever should be down, 66lb setting. Pull lever up to lock in heavy scrub mode, using the heavy scrub mode will reduce run time use only when needed.



ADJUST WATER FLOW



PUSH BUTTON TO START VACUUM MOTOR



PULL CONTROL HANDLE BAIL BACK to engage brush or pad to start scrubbing.



PULL LEVER UP TO LOCK IN HEAVY SCRUB MODE. Pull lever up to lock in heavy scrub mode, using the heavy scrub mode will reduce run time use only when needed.



CHECK SOLUTION LEVEL in recovery tank, empty when needed, also watch for foam and add defoamer if needed.



CHECK BATTERY METER, AND THE SITE TUBE. Empty recovery tank when full in proper drain.



REFILL SOLUTION TANK if needed repeat steps 1-3.



WHEN FINISHED SCRUBBING empty recovery tank and rinse out tank, leave lid open to dry. Also drain and rinse solution tank. Charge batteries if needed. Store scrubber with brush pad holder removed and squeegee lifted up.

MORE DETAILED INFORMATION ON HOW TO OPERATE TRIPLE S AUTOMATIC SCRUBBERS CAN BE FOUND IN YOUR TRIPLE S OWNER'S MANUAL.